Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/Client 50005DE8488/1

Work Order Type: Weatherization Audit Name: Audit DE8488

CLIENT INFORMATION

Client Name: Address:

Client ID: Client 50005DE8488

Alt. Client ID:

AGENCY INFORMATION

Agency: 50005DE **Agency Phone:** (901) 476-5226

Address: P. O. BOX 634, 915 HWY 51 SOUTH **Fax:** (901) 476-5258

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Measures

I	Measure 1 Pa	tch 1' x 2 area in Bedroo	m #2 ceili	ng	Componen	ts		ı	Inspected
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					
0	ther Detail								
				Measur	e Sub Total:] ;	Sub Total:	
1	Measure 2 Pa	tch 2' x 2' area in bathro	om ceilinç	9	Componen	ts			Inspected
	Measure 2 Pa	tch 2' x 2' area in bathroo	om ceilinç	9	•				Inspected
C	omment				Estimated		Ofv	Actual	
<i>C</i> :		tch 2' x 2' area in bathroo Description / Comment Misc Material	om ceiling Units Each	Qty 1	•		Qty		Inspected Total
C #	omment Material / Labor Unspecified	Description / Comment	Units	Qty	Estimated		Qty	Actual	
C # 10	omment Material / Labor	Description / Comment	Units	Qty	Estimated		Qty	Actual	
# 10	omment Material / Labor Unspecified	Description / Comment	Units	Qty	Estimated		Qty	Actual	
# 10	omment Material / Labor Unspecified	Description / Comment	Units Each	Qty 1	Estimated			Actual	

	Pato	ch 2' x 3' area in Bedroo	om #1 ceil	ing	Compone	nts		ı	nspected
Comment					Estimate	1		Actual	
# Material / L	.abor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecifie	ed	Misc Material	Each	1					
Other Detail									
				Measur	e Sub Total:]	Sub Total:	
Field Notes	s:								
					_				
Measure 4		tration Redctn	2		Componei	its		1	nspected
		ILTRATION MEASURES all windows 1-17	5						
2	2. Tape	all duct ends to - plenum	n return air	duct					
		nerstrip attic pulldown sta Door Weatherstrip and t							
					Estimate	d		Actual	
# Material / L	.abor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellane Supplies	ous	Infiltration Reduction	Each	1					
Other Detail									
				Measur	e Sub Total:			Sub Total:	
Field Notes);			Measur	e Sub Total:			Sub Total:	
Field Notes	S:			Measure	e Sub Total:] ,	Sub Total:	
Field Notes	s:			Measur	e Sub Total:			Sub Total:	

Report Run On: 5/23/2010

Measure 5 DW Comment	H Pipe Insulation			Componen				Inspected
# Material / Labor	Description / Comment	Units		Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
	Description / Comment	Each	Qty 1	Unit Cost	TOTAL	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail						,		
			Measur	e Sub Total:			Sub Total:	
Measure 6 DW Comment	H Tank Insulation			Componen Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equipment	DHW Tank Insulation	Each	1					
2 Labor	DHW Tank Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

	Measure 7 Attic	Ins. R-30			Componen	ts 1655	Sq.ft		Inspected
C	Comment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	1655					
2	Labor	Attic Insulation - Blown Cellulose - R-30	SqFt	1655					
(Other Detail						1		
				Measure	Sub Total:			Sub Total:	
	Field Notes: Measure 8 Repl	lace Htg. System			Componen				Inspected
C	Recomn	vner has HVAC gas systened replacing one space ater with 10 ft of gas line	e heater v	vith a d	ouble 50,00 cond gas he	0 BTU Ve eater			
44	Matarial / Labor	December / Comment	l lmita		Estimated			Actual	Total
	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipment	Space Heater - 25 kBtu/h NG Existing, 60 - 84 kBtu/h NG Post	Each	1					
2	Labor	Space Heater - 25 kBtu/h NG Existing, 60 - 84 kBtu/h NG Post	Each	1					
(Other Detail								
				Measure	e Sub Total:			Sub Total:	
	Field Notes:								

Measure 9 CO	Monitor is Needed			Componen	ts		ı	Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	CO monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						1		
			Measur	e Sub Total:]]	Sub Total:	
Field Notes:				L				
	Moisture Problems Evidual Section piping in attic lead	-	-	Componen				Inspected
				Estimated			Actual	
# Material / Labor1 Health and Safety Items	Description / Comment Equipment	Units Each	Qty 1	Unit Cost	Total	Qty	Unit Cost	Total
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	
Field Notes:				e Sub Total:			Sub Total:	